




Lead Free PT Assemblies



Part Number	Connections	A	B	C	Hex
PT-0.50S-LF	1/2" x 1/2" Sweat	1-3/4"	2-1/4"	1-3/4"	1-1/8"
PT-0.75S-LF	3/4" x 3/4" Sweat	2-1/4"	2-3/8"	1-3/4"	1-1/4"

Lead Free Brass Body and PT

Complies with Section 1417(d) of the Safe Drinking Water Act

Meets the lead content requirements of Section 116875 of the California Health & Safety Code